



Total Quality. Assured.

545 E Algonquin Road, Suite H
Arlington Heights, IL 60005 USA

Telephone: 847-439-5667
intertek.com

Published: 25-Nov-24
Revised:

Public Notice ID: 2024-81
Page 1 of 2

Safety Concern with Intertek Certified Product

AirJet and HydroJet Spa Pumps

Notification Type:	Safety
Certification Type:	ETL Listed - US

Notification

Intertek notifies consumers, retailers and distributors of a potential safety concern involving the Intertek Certified products identified below.

Company Identification

Bestway (Hong Kong) International Ltd., of China

Product Identification

The recalled products are AirJet and HydroJet Spa Pumps model numbers P05332, P05339, P05711, P05807, P07000, P07001, P05511, P07034, and P07572. "Bestway" and the model number are printed on the label on the side or back of the spa pump these products are labeled and using an ETLus Certification Mark control number 4006936, Recall number: 24-359 see link to CPSC at https://www.cpsc.gov/Recalls/2024/About-866000-AirJet-and-HydroJet-Spa-Pumps-Recalled-Due-to-Fire-Hazard-One-Death-Reported-Manufactured-by-Bestway-and-Sold-with-SaluSpa-Coleman-and-Hydro-Force-Spa-Liners?utm_campaign=&utm_content=&utm_medium=email&utm_source=govdelivery&utm_term=20240913

Product Photos on Page 2.

Hazard Involved

The recalled AirJet and HydroJet spa pumps can overheat causing the plastic housing to ignite, posing a fire hazard.

What To Do

Use of these products should be immediately discontinued and return to the Applicant for replacement or repair. Distributors and retailers should discontinue sales and return inventories to their suppliers.

Published: November 25, 2024
Revised:

Public Notice ID: 2024-81
Page 2 of 2

Photos and Images / Photos et images



Recalled AirJet Spa Pump model number located on label on side of unit